

Workshop



Please follow the instructions of the staff and observe the following precautions when using the workshop to improve the efficiency of your research.

To use the workshop, you need to attend the equipment use workshop.

◎ IC card (student ID, staff ID) is required to enter.

Available weekdays 9:00-17:00 ※If the work is not completed, the room is available until 20:00.

If the workshop staff is not available, ensure that more than one person is present in the room.

◎ Wearing lab coats, working in sandals, and bringing in food and drinks are prohibited.

After work, 4S (Seiri, Seiton, Seiketsu, and Seiso) are to be carried out.

◎ You may only use equipment for which you have received operating instructions at the workshop.

Using lathe or milling machine is more dangerous, so you need to attend the special seminar.

◎ Use of Machinery

◆ Always wear protective gear when operating machinery.

◆ Please fill in the workshop's machinery user log with the information requested.

(The logs are used to charge usage fees for the maintenance of the workshop.)

◆ Notes. • Never touch rotating/sliding objects and parts of equipment.

• Do not disable any safety features on machinery without permission.

• Do not perform any tasks that exceed the machinery's operating capacity.

• Comply with the warnings displayed on each machine.

(Do not perform any tasks that you cannot handle with confidence.)

◎ The workshop's measuring instruments should be used only in the workshop.

If it is unavoidably necessary to use the measuring instruments in a place other than the workshop, fill in the workshop's measuring instrument checkout log.

◎ Notify the workshop staff immediately regarding any machinery malfunctioning or damage. (If the workshop staff is not available, you may notify him by e-mail.)

Workshop staff : Makoto Watanabe (Work on Tuesdays, Wednesday and Thursdays.)

Phone : 04-7136-3867 (ext. 63867) /E-mail : m-watanabe@edu.k.u-tokyo.ac.jp